

제품 사양서

■ 제품명 : Torquemeter & Indicator

■ 제품사양

1) Non-Contact mV/V Output Strain Gage type Torquemeter

NO.	Article	Specifications
1	Torque range	80,000 N-m
2	Torque Overload	350,000 N-m
3	Speed Rating	0~±3000 RPM
4	Installation method	Flange type
5	Accuracy(% of F.S.)	≤±0.05 %
6	Output signal	Torque : ±10 Vdc, FM

2) Indicator

NO.	Article	Specifications
1	Display	Torque / rpm
2	Torque / rpm / Power (HP)	3 Vrms
3	Power	18-30 VDC
4	Output	Auto-scale ±10 Vdc Analog Output